ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0030, W0031, W0029, W0038, W0033, W0037	NA	Anjaneya Temple Abbigere Old village
Segment No.	**Total Length (m)**	
12/C-W0030/S013934	288.02	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	83.10	77.523569	13.077005	77.524320	13.076856	Abbigere	Old Village
2	204.92	77.521719	13.077818	77.523588	13.077548	Abbigere	7th Cross

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains at Anjaneya Temple area Abbigere, in Ward No.12, in Shettyhalli Sub Division	5000000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	RCC drain & Covering slabs
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender		012-17-000009
Work Order No.	**Work Order Date**	**Period of Extention**
NO:BBMP/EE/DD/WO/118/2017-18	21/06/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/02/2018	23/02/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M//s KRIDL		0.00
Phone No.	**E-Mail ID**	
9448034435		

Field Inspection Details

Number of Trees	Any Other Information	Name
6		SURESH
Date of Inspection	**Remarks**	
27/02/2018	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0030, W0031, W0029, W0038,

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0030, W0031, W0029, W0038, W0033, W0037	NA	Anjaneya Temple Abbigere Old village
Segment No.	**Total Length (m)**	
12/C-W0030/S013934	288.02	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	83.10	77.523569	13.077005	77.524320	13.076856	Abbigere	Old Village
2	204.92	77.521719	13.077818	77.523588	13.077548	Abbigere	7th Cross

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains at Anjaneya Temple area Abbigere, in Ward No.12, in Shettyhalli Sub Division	5000000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	RCC drain & Covering slabs
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender		012-17-000009
Work Order No.	**Work Order Date**	**Period of Extention**
NO:BBMP/EE/DD/WO/118/2017-18	21/06/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/02/2018	23/02/2019	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M//s KRIDL		0.00
Phone No.	**E-Mail ID**	
9448034435		

Zone: DASARAHALLI **Ward No:** 12 **Ward Name:** Shettihalli **Street ID:** W0030, W0031, W0029, W0038,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರಾಜೇಂದ್ರನಗರ, ಬೆಂಗಳೂರು